ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

## BBMP ENGINEERING DEPARTMENT

## Road History Data Sheet

### General

| Zone | Ward No. | Ward Name |
|---|---|---|
| DASARAHALLI | 12 | Shettihalli |
| **Street ID** | **Street Name** | **Significant Landmark** |
| W0267 | Maheshwari Nagar Ambedkar Rd | Opposite Medarahalli masjid |
| **Segment No.** | **Total Length (m)** | |
| 12/S-W0267/S014842 | 127.16 | |

**Segment Details**

| Seg No. | Length (m) | Start Coordinates | | End Coordinates | | From | To |
|---|---|---|---|---|---|---|---|
| 1 | 127.16 | 77.511925 | 13.071472 | 77.511835 | 13.070597 | Medarahalli main road | W0271 1st cross |

### Work Details

**History of Road / Lane / Circles**

| Name of the Work | Sanctioned Estimated Amount (Rs.) | Sanctioned Year |
|---|---|---|
| Improvements to roads and drains at drains at Medarahally village main road and surrounding area in Ward No.12 Shettyhalli Sub Division | 5000000 | 2017 |
| **Year** | **Type of Work** | **Other Work Type** |
| 2017 - 2018 | Others | drain work |
| **Tender** | **Work Details** | **Job No. / Work Code** |
| Not a Tender | RCC drain constructed to Road ID no. W0271, W0267 and cross roads and 3 nos CD's constructed. | 012-18-000003 |
| **Work Order No.** | **Work Order Date** | **Period of Extention** |
| 35/18-19 | 11/09/2018 | |
| **Defect Liability Period From** | **Defect Liability Period To** | **Multiple road involved with the same Job No/ Work Code #** |
| 26/10/2018 | 25/10/2019 | Yes |

### Contractor Details

| Name of Contractor | Contractor Reg No (BBMP/PWD) | Expenditure Booked \ Released (Rs) |
|---|---|---|
| M/s Technical Manager (West), KRIDL | | 4997455.00 |
| **Phone No.** | **E-Mail ID** | |
| 9845009297 | | |



Scanned by CamScanner

## Field Inspection Details

| Number of Trees | Any Other Information | Name |
|---|---|---|
| 0 | | Shiva Kumar |
| **Date of Inspection** | **Remarks** | |
| 04/08/2019 | | |

| Category | Image | Photo Remark |
|---|---|---|
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |
| Drain Condition | | This photo seems out of range. |

## Remarks

| Designation | Approver Name | Date | Target Date | Remark |
|---|---|---|---|---|
| CE | DODDAIAH | 04/08/2019 | 30/09/2019 | |
| EE | jayalingappa | 04/08/2019 | 30/09/2019 | |
| AEE | Jayalingappa | 04/08/2019 | 30/09/2019 | |
| AE | Shiva Kumar | 04/08/2019 | 30/09/2019 | |
| AE | Shiva Kumar | 03/08/2019 | 30/11/2018 | |



AE.12-12

Scanned by CamScanner